


Net Parameters with No Value

Modified by Jason Howie on May 8, 2015

Parent category: [Violations Associated with Nets](#)

Default report mode:  Warning

Summary

This violation occurs when a parameter set object is attached to a net object (wire or bus) and at least one of the defined parameters in the set has no value assigned to it.

Notification

If compiler errors and warnings are enabled for display on the schematic (enabled on the **Schematic - Compiler** page of the *Preferences* dialog) an offending object will display a colored squiggle beneath it. A notification is also displayed in the *Messages* panel in the following format:

Invalid net-parameter value at *<Location>*,

where

Location is the X,Y coordinates for the hotspot of the parameter set object associated to the net.

Recommendation for Resolution

Access the *Parameters* dialog for the offending parameter set object, and ensure that all parameters defined within have a value assigned to them. If the offending constituent parameter is not required, simply remove it from the set.

Source URL:

[http://documentation.circuitmaker.com/display/CMAK/WorkspaceManager_Err-NetParametersWithNoValue\(\(Net+Parameters+with+No+Value\)\)_CM](http://documentation.circuitmaker.com/display/CMAK/WorkspaceManager_Err-NetParametersWithNoValue((Net+Parameters+with+No+Value))_CM)